

BUILDING SAFETY CERTIFICATE

No: 376 | 2023-24.

Dated: 22/01/2024

Certified that the existing building **WINMORE ACADEMY** (Name Of The Building Or Premises) at **No.13/1, Bhaktharahalli Village, Naduvathi Post, Hoskote Taluk, Bangaluru-67** (address) Comparised of **Ground and First Floors** Owned /Occupied by **Winmore Academy, No.13/1,Bhaktharahalli Village, Naduvathi Post, Hoskote Taluk, Bangaluru-67**(name of the instution)have complied with the Building Safety requirements in accordance with National Building Code Rules and Verified by the Officers Concerned Of **Public Works Department (PWD)** on **Dated:10.01.2024** (Date Of Inspection) in the Presence Of **Principal,Winmore Academy, No.13/1, Bhaktharahalli Village, Naduvathi Post, Hoskote Taluk, Bangaluru-67** (name and addresses of the Manager/Secretary or his representative)and that the building /premises is Fit for Occupancy upto Classes **X (10th Standard)** (X/XII) With Effect From an Period Of 3 Years in Accordance With test Conducted and Issued Building Safety Certificate by **HENCON ASSOCIATES,Bengaluru** on **23.11.2021** rule and Subject to Compliance of the Specific Condition as appended

1. Non-Structural Elements (Infrastructural Facilities) like Health Certificate.
2. Fire Safety Certificate has to Endorsed.
3. Drinking Water and Sanitary Certificate Has tobe Endorsed by RWS Department.

Issued on **22.01.2024** at **PWD Sub Division Hoskote-562114** by

(Sagar.C.)

Assistant Engineer.
PWD,SubDivision,Hoskote



(Prakash.T)

Assistant Executive Engineer.

PWD,Sub Division ,Hoskote
ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಇಂಜಿನಿಯರ್
ಪುನಃಪರಿಶೀಲನೆಯಾಣಿ ಇಲಾಖೆ, ಶಾಸನ ಬಿಳಾರ,
ಹೊಸಕೋಟೆ-562114